



AVEVAWORLD

ACCELERATE INDUSTRIAL INTELLIGENCE



AVEVA WORLD

Predictive Analytics *PE6000* | *LM6000* | *LM2500*

Brian Roth
VP O&M

PROENERGY

LIFECYCLE CARE

For the Life of the Turbine

Advanced Monitoring and
Predictive Solutions (AMPS)


Depot Services

Lease Engines

Remote Operating
Centers (ROCs)

O&M Services

Technical Services



THE NEED TO DEVELOP TECHNOLOGY

Operating the World's Largest Aero Fleet and More



HO Clarke

384 MW



Mark One

384 MW



Topaz

480 MW



Brotman

384 MW



Braes Bayou

384 MW



Remy Jade

384 MW

Reliability

99%

Across 6 sites in 2025

Starts


11,000

MWh Generated

2.7M+

AVEVA™ Solutions

- AVEVA™ PI System™
- AVEVA™ Predictive Analytics
- AVEVA™ PI Vision™
- AVEVA™ PI DataLink™
- CONNECT Data Services

An aerial photograph of an industrial facility, possibly a refinery or chemical plant, with several large storage tanks and processing units. A large white triangle is overlaid on the image, divided into four sections. The background is a dark blue gradient.

PREDICTIVE REPORTING

A red and blue diagonal bar.


LEVERAGE TOTAL CARE VALUE

AMPS

**CUSTOMER
EXPERIENCE**

**SERVICE
ENGINEERING**

**FIELD
SERVICES**



ADVANCED MONITORING AND PREDICTIVE SOLUTIONS (AMPS)

Drive Profitability With Data Intelligence

Predicts potential issues before traditional alarms activate

Sends prescriptive advisories on immediate actions to take

Helps you to plan outages and maintain uptime

Advanced Monitoring

Alerts Before
Alarms


70+ analytics

Automated
Notifications


Operational &
Trip Advisories

Encourage
Dialogue

Feedback
process



Predictive Solutions



AMPS Advanced Monitoring & Protection System **PROENERGY**

Warning
TLO Sump C Temp High

12/03/2023 9:45 PM (UTC)

Case Number

Site: APZ1 Unit: Unit 01 Engine Model: LM6000
 N25: 10174 rpm Temperature: - Unit MW: 22.01 MW

Observation:

The AMPS Center has identified that the C-Sump Temperature for TLO Scavenge has surpassed the monitored setpoint of 310 °F. The current temperatures are shown below.
 The standard operating range is 290-320°F, and the alarm setpoint is fixed at 320°F. This deviation could point to various potential issues, including low tank level, insufficient oil sump flow, malfunctioning sensor(s), obstructed scavenge pump inlet screens, high oil supply temperature, sump airtight seal failure, or bearing failure.
 Should both sensors be lost, an automatic deceleration to minimum load will be initiated.

Online Recommendation:

1. Conduct a visual inspection of the unit to identify any leaks or obstructions.
2. Verify that the levels of TLO/GLO oil tanks are within the normal range.
3. Ensure that the temperatures of TLO/GLO oil tanks are within the specified normal operating limits.
4. Confirm that oil supply pressures and temperatures are within the acceptable normal operating limits.
5. Verify that the oil filter differential pressures (DPs) are within the normal operating limits.
6. Verify that temperatures in other sumps conform to the specified operating limits.
7. Ensure that chip detectors consistently read the full ohm value without fluctuations.
8. Confirm that vibrations are within acceptable limits.

Offline Recommendation:

1. Refer to Table 8.5, Group 6 / Table 8.6, for troubleshooting guidance in addressing Temperature Sensor/Cabling issues. Perform necessary repairs or replacements as per MP-1035.
2. Conduct an inspection of the TLO Sump to ensure the proper oil level.
3. Confirm that the TLO Supply Temperature falls within the designated normal operating range.
4. Verify that the TLO Scavenge Pump Discharge Pressure is within the acceptable normal operating range.
5. Inspect TLO Scavenge Pump Filter for debris, clean or replace as required.
6. Inspect and clean scavenge pump inlet screens per MP-4011 as required.
7. Inspect and clean individual chip detectors per MP-4008.

Comments:

TC FROM INLET AMBIENT TEMP TT84299: 82 °F TLO-SUMP C SCAV OIL TEMP - B TE6186B: 302 °F TLO-SUMP C SCAV OIL TEMP - A TE6186A: 301 °F

CASE STUDIES

A NEW BUSINESS INPUT



PREDICTIVE SOLUTIONS

Detected Failures >30 Days Early In Peaking Units

Key points in the compressor showed degradations from normal operations.


- Pressures
- Temperatures
- VG systems
- Measured from June 20 to Nov. 15, 2022
 - 1 minute frequency
 - 135 variables for each of the 2 units

Asset Name	Description	Identified by Predictive Analytics	Early Warning
BRAES Unit 3	HP Compressor Performance	Yes	38 Days
BRAES Unit 4	HP Compressor Performance	Yes	34 Days



CASE STUDY #1


Compressor Issue Detected 38 Days Early



CASE STUDY #2

Alert:

**B SUMP SCAVENGE
TEMPERATURES
ROSE ABOVE
NORMAL.**




CASE STUDY #3A


Alert:

**WIDE-BAND TRF
VIBRATION
INCREASING WITH T3
TEMPERATURE**

LP TRF




HP TRF



CASE STUDY #3A

Result: Preventive Maintenance Saves \$425K



Procedure No. MP-4004 Gas Turbine Exhaust Inspection
Gas Turbine Exhaust System Inspection

Unit 8

Rev. 1.0

NOTE: Exhaust duct alignment should be checked after final full engine alignment is complete.

1. Measure and record dimension A and dimension B at eight equally spaced locations around circumference of exhaust duct. Calculate X as follows:

$$XA = AMAX - AMIN$$

2. Refer to table 1 for the applicable limits. If dimensions exceed the table maximum or minimum values, then adjust the exhaust diffuser. Refer to packager's manual.

Table 1. Exhaust System Limits


	Minimum Value	Maximum Value	Maximum X _A
Dimension A (Measured at Outer Piston Ring)	2.775 in. (70.49 mm)	N/A	0.25 in. (6.35 mm)
Dimension B	0.14 in. (3.56 mm)	N/A	N/A
DIM A		DIM B	
1. 2.775		1. .250	
2. 2.780		2. .250	
3. 2.780		3. .200	
4. 2.790		4. .105	
5. 2.790		5. .105	
6. 2.800		6. .090	
7. 2.790		7. .105	
8. 2.775		8. .225	
9. AVG 2.785		9. AVG .153	

CASE STUDY #3B


Alert:

**SIGNIFICANT SPIKE
IN VIBRATION
DURING STARTUP
AND SHUTDOWN**

CRF Wideband



TRF Wideband




CASE STUDY #3B

Result: HPC and Midshaft Warning Saves \$2.5M



Stage 5 HPC Blades



Stage 3 Blade LPC




Stage 8 HPC Blades



Rotor spool vane contact



Crack in the inner section of the threaded end of the midshaft



Crack in the outer section of the threaded end of the midshaft

PROENERGY enables predictive decision making in reactive peaking operations

Challenge

- Dispatch uncertainty and frequent starts drove a reactive operating model
- Engines with existing hours and incomplete pedigree increased reliability risk
- Alarm-based monitoring identified problems too late for preventive intervention
- Staffing focus and alert execution initially limited the impact of early analytics

Solution

- ProEnergy used AVEVA™ PI System™, AVEVA™ Predictive Analytics, AVEVA™ PI Vision™, AVEVA™ PI DataLink™, and CONNECT data services to detect issues earlier and guide proactive operational decisions.

Results

- **Detected compressor degradation and emerging failures more than 30 days earlier than traditional alarm-based approaches**
- **Avoided a major high-pressure compressor and midshaft failure valued at \$2.5M**
- **Prevented additional damage events delivering \$425K–\$600K in cost avoidance across multiple units**
- **Improved operational confidence by enabling earlier, better-informed maintenance and business decisions.**



AVEVAWORLD

Thank You