



Behringer MS-101 Firmware

Version 1.1.2 - (17 May 2019)

Addressed Issues

Item	Issues Description	Solution
1	Sequencer response to external sync was not configurable.	This is now configurable. F0 00 20 32 00 01 02 1D 01 F7 -- Activate F0 00 20 32 00 01 02 1D 00 F7 -- Deactivate
2	Sequencer would skip the first step when synced with external MIDI clock.	This has been corrected.
3	One key triggered dual note in the first loop of ARP.	This has been corrected.
4	Latency in ARP mode.	This has been improved.
5	Sequencer Playback Direction	This function has been improved to bi-directional. Forward playback: Press "PLAY/STOP" button to start the sequencer. Reverse playback: Press "SHIFT" + "PLAY/STOP" buttons to start the sequencer.