

Behringer Speaker Firmware Update (06 Jan 2020)

MPA200BT (V1.2.2) & B12X/ B15X (V1.2.1)

Addressed Issues

Item	Issues Description	Solution
1	Don't comply new Bluetooth chipset.	Update firmware to solve this issue.

musictribe.com behringer.com