Behringer ODYSSEY Firmware

Version 1.2.0 (03 Nov 2022)

Item	Issues Description	Solution
1	It is not possible to control data flow from "MIDI IN" to "MIDI OUT" and USB. This's unusable for customers when used with DAW's and other external sequencers	Add a soft-switch to support switching the "MIDI THRU" feature on and off using new SynthTribe App