

Behringer SKIES Firmware

Version 1.0.5 (29 SEPT 2025)

We've just released a small but important update (v1.0.5) for the SKIES.

What's New

- Mode 2 (Pitch shifter/time-stretcher) functionality issue resolved.

How to Update

Download the latest Synthtribe app to perform the upgrade.

Thanks to our users for your feedback—this update includes fixes and improvements raised by the community. More updates and features are in development!

These release notes are provided by Music Tribe Global Brands Ltd. ("Music Tribe") for informational purposes only and are subject to change without notice. Music Tribe makes no representations or warranties, express or implied, as to the accuracy, completeness, or suitability of the information contained herein. These release notes apply only to the firmware version explicitly stated and may not apply to previous or future firmware versions.

Installation and use of firmware updates are at the user's own risk. Firmware updates should only be installed by qualified users or authorized personnel in accordance with the product documentation. Users are solely responsible for backing up all data and ensuring system compatibility prior to installation.

Any features or improvements listed are provided "as is" and may be modified or removed in future versions. This document does not constitute a warranty, service agreement, or commitment of future functionality, and shall not modify or extend any warranty provided by Music Tribe.

For the most up-to-date firmware documentation and technical support resources, please visit: community.musictribe.com

All trademarks are the property of their respective owners.
© 2025 Music Tribe Global Brands Ltd. All rights reserved.