

Behringer POLY D Firmware Update

Version 1.1.3 (17 Jan 2025)

Enhanced Clock Divide Functionality:

- When the synthesizer is clocked to an external source, the TEMPO control now allows you to adjust the clock division from 1/4 to 1/32T.
- Note: Adjusting the clock division while a sequence is playing will result in a loss of sync timing. To avoid this, stop the sequence before making changes to the clock divide setting.

Clock Divide Adjustment via SynthTribe:

- The clock division can now be configured directly in the SynthTribe app under the sequencer settings page, offering a more intuitive adjustment process.

Arpeggiator Playback Improvements:

- The arpeggiator playback has been optimized to ensure smoother and more consistent performance during operation.