


Update Guide




Service Support Bulletin

1. Update unit with USB-AB

1.1 Open "SynthUpdater.exe"




1.2 Press "Open File" to load file




MS101 VCO & CV

Calibration Procedures

1.3 Wait for connect



1.4 Press "Start Update" to download



1.5 Wait for finished

