

# Changelog

---

## [3.1] - 2024-08-12

### Added

- support for new PLL

### Changes

- delayed phantom power-on (to avoid psu overload)

## [3.0-1] - 2024-04-17

- files updated to fix surface/pad device not found issues

## [3.0] - 2024-01-16

### Added

- support for Wing protocol (use of Wing on both ports)
- stereo phones mode (monitor mode), hold CFG and press encoder to enable/disable, hold gain and turn encoder to select aes50 channel pair
- new split modes supporting 2 or 3 stacked units
- converter mode (master, ADC out on ADAT and P16)

### Changed

- selected phones channel stored in persistent memory
- removed 'analogue snake replacement' modes (user needs to stay on 2.x if these are required)

### Fixed

- sporadic connection issues on port B (on old hardware only)