

Behringer MODEL 15 Firmware Update

Version: 1.3.7 (24 Sep 2024)

Bug Fixes:

- MIDI message forwarding errors have been fixed

New Feature:

- SEQ play on clock start (available for selection in Synthtribe)
- MIDI Through control (available for selection in Synthtribe)